

MODIFICATION INSTRUCTIONS for the **Kodak X-Omat MULTILOADER 7000** **Service Code: 3444**

Modification No. 6 Type 1 Required

Purpose: To prevent air leakage in the WATER TRAP AY. The air leakage caused the error code "MS C0".



Important

Qualified service personnel must install this modification.

Service Effects: None

Special Requirements: None

Serial Numbers: 1001 - 1514

Installation Time: 1 hour

Special Tools: None

Parts Status: Available from Service Parts Management.

Parts Requirements: See [Page 2](#).



HEALTH IMAGING

Confidential
Restricted Information
© Eastman Kodak Company, 2003

PLEASE NOTE

The information contained herein is based on the experience and knowledge relating to the subject matter gained by Eastman Kodak Company prior to publication.

No patent license is granted by this information.

Eastman Kodak Company reserves the right to change this information without notice, and makes no warranty, express or implied, with respect to this information. Kodak shall not be liable for any loss or damage, including consequential or special damages, resulting from any use of this information, even if loss or damage is caused by Kodak's negligence or other fault.




This equipment includes parts and assemblies sensitive to damage from electrostatic discharge. Use caution to prevent damage during all service procedures.

MODIFICATION KIT 1F6304 includes:

Part No.	Description	Quantity
1F6571	FILTER AY	1
1F6226	ELBOW CONNECTOR - swivel	1
1F6305	GREASE	1
952960	PIPE THREAD TAPE	1
7C8765	REIMBURSEMENT CARD	1
1F6876	MODIFICATION INSTRUCTIONS	1

Installing the Modification



H186_2162GCA
H186_2162GC

[1] De-energize the MULTILOADER 7000.


[2] Remove the left SIDE PANEL.

[3] Remove:

- MOUNTING CLIP
- HOSE CLAMP

[4] Remove and discard:


- NUT
- HOSE
- ELBOW CONNECTOR



H186_2163GCA
H186_2163GC

[5] Carefully bend the end of the CONDENSER COIL to a vertical position.

MODIFICATION INSTRUCTIONS, TYPE 1




[6] Install:


- new ELBOW CONNECTOR
- FILTER AY

[7] Fasten:

- HOSE CLAMP
- MOUNTING CLIP



[8] Remove one DRAIN AY.



[9] Disassemble the DRAIN AY.

[10] Discard the SPRING.

[11] Use a cloth to clean:

- inside the top of the DRAIN AY
- SEAL
- O-RING
- bottom of the DRAIN AY

[12] Apply the GREASE around the indicated inside surface.



Caution

Observe the correct position of the PLUNGER when you assemble the DRAIN AY.

[13] Assemble the DRAIN AY.

[14] Wrap PIPE THREAD TAPE around the THREAD.

[15] Install the DRAIN AY.

[16] Do Steps [8](#) to [15](#) for the remaining DRAIN AY.

Completing the Modification

[1] Energize the MULTILOADER 7000.

[2] Check for air leakage. See ADJUSTMENTS AND REPLACEMENTS 5E9999:

Section	Procedure
ADJUSTMENTS	Pneumatic Pressure

[3] Assemble the MULTILOADER 7000.

[4] Process films to check for correct operation of the MULTILOADER 7000.

[5] Circle "6" on the MODIFICATION LABEL.

[6] Record the information for feedback:

K-number	Service Code	Serial No.	Activity Code	Installation Time	Part No.
	3444		M06		1F6304

Publication History

Publication Date	Publication No.	ECO No.	Changed Pages	File Name	Notes
28MAR03	1F6876	2665-088	---	1f6876.fm	New Publication

Kodak and *X-Omat* are trademarks.